OUT60438

| S | E | С | R | E | T | 19g152Z | CITE | S | 102 | 1966 NOV | 19 |
|---|---|---|---|---|---|---------|------|---|-----|----------|----|
| | | | | | | | | | | | |

1. CAMERA B 23 WAS USED IN MISSION G 926 FLOWN ON 15
NOVEMBER 1966. PROCESSING WAS ACCOMPLISHED BY NAV RECONTECH
SUPPCEN.

- 2. OR IGINAL NEGATIVE
 - A. THE DENSITY IS NORMAL AND THE RESOLUTION IS GOOD.
- PRESENT ALONG THE INBOARD EDGE. NUMEROUS LONGITUDINAL PLUS
 DENSITY LINES ARE NOTED THROUGHOUT. HEAT SPLICES ARE LOCATED
 BETWEEN FRAMES 123/124, 1097/1098, 2066/2067 AND IN FRAME 1422
- C. 9L SIDE: EDGE STATIC IS PRESENT ALONG BOTH EDGES OF THE FILM. EDGE FOG IS NOTED ONLY ALONG THE INBOARD EDGE.

 THREE ROWS OF MINUS DENSITY DOTS APPEAR ON THE FIRST TEN FRAMES. THE DOTS ARE SPACED 1.7" APART. THE FIRST ROW IS LOCATED 3.7" FROM THE INBOARD EDGE. THE SECOND ROW APPEARS 2.7" FROM THE INBOARD EDGE AND THE THIRD ROW IS LOCATED 2.2" FROM THE OUTBOARD EDGE. ONLY THE SECOND AND THIRD ROWS ARE PRESENT ON FRAMES 11 TO 102. ONLY THE SECOND ROW APPEARS ON FRAMES 121 TO 352. ROLLER CHATTER APPEARED INTERMITTENTLY ALONG BOTH EDGES. A PLUS DENSITY LINE IS PRESENT 2.3" FROM THE INBOARD EDGE OF FRAMES 365 THRU 920. MANY FINE PLUS DENSITY LINES ARE PRESENT BETWEEN FRAMES 1364 THRU 1382. HEAT SPLICES ARE LOCATED IN FRAME 1178 AND BETWEEN FRAMES 2138/2139.

Sanitized

02 25X1

25X1

1/1_1



- D. BOTH SIDES: FRAME 946 WAS SMEARED AND PROBABLY CAUSED BY VEHICLE MANEUVERS. IN SEVERAL VERTICAL FRAMES THERE IS A VERY SLIGHT CHANGE IN DENSITY LOCATED APPROXIMATELY 3.2" FROM THE DATA BLOCK. IT IS PROBABLY CAUSED BY A REFLECTION IN THE WINDOW OR AN INTERNAL CAMERA REFLECTION. THIS ANOMALY HAS BEEN REPORTED BEFORE. THE LAST TITLED FRAME IS 2225.
 - E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.
 - 3. pOSITIVE:
 - A. PI SUITABILITY IS GOOD.
 - B. PRINTING AND PROCESSING WERE GOOD.
- C. CLOUDS OBSCURE OR DEGRADE APPROXIMATELY 45 PERCENT OF THE MISSION.

SECRET

-- END OF MESSAGE--